

220-701 A+

CompTIA CompTIA A+ Essentials (2009)

Practice Exam: 220-701 Exams

Exam Number/Code: 220-701

Exam Name: CompTIA A+ Essentials (2009)

Questions and Answers: 852 Q&As

([A+](#))



Exam : [220-701](#)

"CompTIA A+ Essentials (2009)", also known as 220-701 exam, is a CompTIA certification. With the complete collection of questions and answers, TestInside has assembled to take you through 852 Q&As to your 220-701 Exam preparation. In the 220-701 exam resources, you will cover every field and category in CompTIA Certification helping to ready you for your successful CompTIA Certification.

Quality and Value for the 220-701 Exam TestInside Practice Exams for CompTIA **A+** Certification 220-701 are written to the highest standards of technical accuracy, using only certified subject matter experts and published authors for development.

TestInside provide the professional Q&A.

1. We offer free update service for three month.

After you purchase our product, we will offer free update in time for three month.

2. High quality and Value for the 220-701 Exam.

220-701 simulation test questions, including the examination question and the answer, complete by our senior IT lecturers and the A+ product experts, included the current newest 220-701 examination questions.

3. 100% Guarantee to Pass Your A+ exam and get your A+ Certification.

If you do not pass the CompTIA Certification 220-701 exam (CompTIA A+ Essentials (2009)) on your first attempt using our TestInside testing engine and pdf file, we will give you a FULL REFUND of your purchasing fee.

use TestInside 220-701 Q&A ensure you pass the exam at your first try.

TestInside professional provide A+ 220-701 the newest Q&A, completely covers 220-701 test original topic. With our complete A+ resources, you will minimize your A+ cost and be ready to pass your 220-701 tests on Your First Try, 100% Money Back Guarantee included!

[CompTIA 220-701](#) Test belongs to one of the A+ certified test, if needs to obtain the A+ certificate, you also need to participate in other related test, the details you may visit the [A+](#) certified topic, in there, you will see all related A+ certified subject of examination.

TestInside Testing Engine Features

Comprehensive questions and answers about 220-701 exam

220-701 exam questions accompanied by exhibits

Verified Answers Researched by Industry Experts and almost 100% correct

220-701 exam questions updated on regular basis

Same type as the certification exams, 220-701 exam preparation is in multiple-choice questions (MCQs).

Tested by multiple times before publishing

Try free 220-701 exam demo before you decide to buy it in Test-Inside.com.

Note: This pdf demo do not include the question's picture.

Exam : CompTIA 220-701

Title : CompTIA A+ Essentials (2009)

1. Which of the following interfaces are typically supported on the input side of a KVM switch?

- A. PS/2, VGA, USB
- B. DB25, DB9, PS/2
- C. PS/2, DB9, USB
- D. PS/2, DB25, VGA

Answer: A

2. Which of the following types of portable media offers the LARGEST storage capacity?

- A. DVD-DL
- B. CD-RW
- C. CD-R
- D. DVD-R

Answer: A

3. A user reports that their computer suddenly will not boot. When the technician arrives, they discover that the user is very worried they will not be able to complete a research paper they've been working on which is due by the end of the day. Which of the following is an appropriate response to the user's concerns?

- A. A Trojan may have infected the OS or worked its way into the MBR. What did you download recently that caused the problem?
- B. I understand your concern, and will try to have your computer working again as quickly as possible so that you can finish your report.
- C. If the paper was so important to you, you should have created a backup copy so you could finish it on another computer.
- D. I do not understand why you are upset. I am sure your professor will understand and you will be able to turn in the paper tomorrow.

Answer: B

4. The BEST information to document when changing the refresh rate on the display is to include:

- A. the previous refresh rate and the new refresh rate applied.
- B. the method that was used to access the display properties to change the refresh rate.
- C. all the refresh rates that were tested.
- D. the color resolution the user requested as well as the refresh rate.

Answer: A

5. A customer reports that the laser printer produces poor quality printouts. Having arrived onsite, the technician has a discussion with the customer and reviews some examples of their print jobs. Which of the following should the technician do NEXT?

- A. Clean the toner cartridge.
- B. Change the paper.
- C. Replace the fuser.
- D. Print a test page.

Answer: D

6. A technician is installing Windows XP on a system that has a SATA HDD. Which of the following will the technician MOST likely have to do to start the installation?

- A. Press the F8 Key
- B. Press the F3 Key
- C. Press the F2 Key
- D. Press the F6 Key

Answer: D

7. A technician is replacing fifteen 21 CRTs with 19 LCDs. The storage room is on the other side of the building. Which of the following safety measures should the technician take?

- A. Wear a back brace when lifting and carrying the CRTs to the storage room.
- B. Wear anti-static wrist straps to prevent ESD in the new monitors.
- C. Recycle the monitors after removing the capacitors for use in other monitors.
- D. Ask several technicians for help in lift the CRT monitors and use a cart for transporting them.

Answer: D

8. Which of the following connector types is used with twisted pair cable?

- A. T-Connector
- B. BNC
- C. RJ-45
- D. LC

Answer: C

9. Which of the following are valid ports for printing over a network? (Select TWO).

- A. USB 001
- B. \computernamesharename
- C. SNMP
- D. IP_ip_address
- E. IEEE 1394

Answer: BD

10. A technician notices that there is a second partition on the primary hard drive. This partition is not assigned a drive letter and is not accessible from Windows. Which of the following is the MOST likely explanation for this extra partition?

- A. Space reserved by the drive manufacturer for firmware.
- B. Space set aside by Windows for use by the virtual memory swap file.
- C. A potentially dangerous virus has been downloaded onto the system.
- D. A recovery partition put there by the manufacturer.

Answer: D

11. Which of the following BEST describes the function of a DNS server?

- A. Secures network traffic through shared key encryption.
- B. Provides resolution of host names to IP addresses.
- C. Provides security for a network through the use of ACLs.
- D. Dynamically assigns IP addresses for easy client configuration.

Answer: B

12. Which of the following is needed to perform an ASR restore in Windows XP?

- A. Operating system CD
- B. Recovery console
- C. Vendor recovery CD
- D. ERD disk

Answer: A

13. Which of the following is an advantage of upgrading to a 64-bit version of Windows?

- A. A greater number of dynamic disks or disks larger than 1 TB can be supported.
- B. Multiple applications running in 16-bit compatibility mode are supported.
- C. More than 4GB of RAM, in some cases up to 128GB of RAM can be supported.
- D. A new anti-virus protection scheme called Data Execution Prevention is supported.

Answer: C

14. Which of the following printers would be the BEST choice for printing on multi-part forms?

- A. Impact printer
- B. Thermal printer
- C. Inkjet printer
- D. Laser printer

Answer: A

15. Which of the following bus speeds is used for a PCIe card? (Select TWO).

- A. 1x
- B. 3x
- C. 6x
- D. 8x
- E. 24x

Answer: AD

16. Which of the following allows verification of the port that a printer is currently using?

- A. The print queue window from system tray
- B. Properties of the printer from the Printers Control Panel
- C. Print spooler view in the Printers Control Panel
- D. Properties of the port within Device Manager

Answer: B

17. Which of the following features is only available with the Windows XP Professional version as compared to the Windows XP Home version?

- A. Simple File Sharing
- B. Basic Disk Partitions
- C. Remote Desktop
- D. Joining a domain

Answer: D

18. After installing a new SATA hard drive the technician notices the drive is hot to the touch and is giving off a slight odor. Which of the following should the technician do?

- A. Install a larger fan near the hard drive to cool the system.
- B. Clean the drive with compressed air and continue to use it.
- C. Remove and replace the drive.
- D. Apply more thermal compound and reseat the drive.

Answer: C

19. While a technician is responding to a customer's call, a co-worker keeps insisting on telling the technician about their weekend. Which of the following is the BEST course of action?

- A. Ask the customer permission to put them on hold and listen politely to the co-workers stories.
- B. Put the customer on hold just for a few minutes and join the conversation.
- C. Forward the customer to another technician and join the conversation.
- D. Ask the customer permission to put them on hold and politely ask the co-worker to talk later.

Answer: D

20. Which of the following describes the 25 or 9 pin connector with male pins on the back of a laptop computer?

- A. Parallel port
- B. Serial port
- C. IEEE 1394 port
- D. USB port

Answer: B

21. Which of the following hardware is hot pluggable? (Select THREE).

- A. eSATA
- B. Express Card/54
- C. PS/2 peripherals
- D. MIDI devices
- E. NIC
- F. USB

Answer: ABF

22. Which of the following is the maximum FAT32 volume size Windows 2000 and XP will recognize?

- A. Up to 16GB
- B. Up to 32GB
- C. Up to 1024GB
- D. Up to 2048GB

Answer: D

23. Which of the following protocols uses port 80?

- A. SMTP
- B. HTTP
- C. HTTPS
- D. FTP

Answer: B

24. A technician receives a boot error message OS not found. Which of the following should the technician check?

- A. The boot order in the BIOS
- B. If Plug and Play is enabled
- C. If the computer is in Safe Mode
- D. If the BIOS is current

Answer: A

25. A technician needs to assign a default subnet mask for a class B network to a network device that was just installed. Which of the following would the technician use?

- A. 224.0.0.1
- B. 255.0.0.0
- C. 255.255.0.0
- D. 255.255.255.0

Answer: C

26. A user calls and says they cannot get to the Internet. How would a technician walk the user through checking the IP address and default Gateway on the computer?

- A. Start>Run>type ipconfig>click OK and ask user to read the results.
- B. Start>Run>type cmd>click OK>type ipconfig /flushdns>press enter and ask user to read the results.
- C. Start>Run>type cmd>click OK>type ipconfig /release>press enter key and ask user to read the results.
- D. Start>Run>type cmd>click OK>type ipconfig /all>press enter key and ask user to read the results.

Answer: D

27. Which of the following commands verifies connectivity between two hosts? (Select TWO).

- A. chkntfs
- B. dxdiag
- C. tracert
- D. ipconfig
- E. ping

Answer: CE

28. Which of the following BEST describes the initial process of setting up a new operating system from a CD-ROM?

- A. Format a partition, install device drivers, and install the operating system.
- B. Create a partition, format the partition, and install the operating system.
- C. Install the operating system, create a partition, and install device drivers.
- D. Install the operating system, install device drivers, and create a partition.

Answer: B

29. Users are reporting that print jobs being sent to a shared printer are not printing. A technician has verified the printer is online and prints a configuration page from the printer. Which of the following is the MOST likely cause of the issue? (Select TWO).

- A. QoS for printing is not functioning over the LAN.
- B. The printer needs to have a cartridge replaced.
- C. A job in error status is at the top of the print queue.
- D. The printers IP address has changed.
- E. New drivers have been released and need to be installed.

Answer: CD

30. While performing a preventative maintenance check on a personal computer, a technician notices that several unused expansion card slots have open ports. Which of the following BEST describes why the covers for these card slots should be reinstalled?

- A. Help limit radio frequency interference (RFI) inside the case.
- B. Help ensure proper air flow through the case.
- C. Help prevent moisture buildup in the case.
- D. Help limit electrostatic discharge (ESD) inside the case.

Answer: B

[More 220-701 Information](#)

Related 220-701 Exams

[220-602](#) *CompTIA A+ 220-602 Exam (IT Technician designation pathway)*

[220-701](#) *CompTIA A+ Essentials (2009)*

[220-601](#) *CompTIA A+ Essentials 220-601 Exam*

[220-702](#) *CompTIA A+ Practical Application (2009 Edition)*

[220-603](#) *CompTIA A+ 220-603 (Remote Support Tech designation pathway)*

[220-303](#) *A+ Core Hardware Exam - Arabic or Greek only*

[220-604](#) *CompTIA A+ 220-604 Exam (Depot Tech designation pathway)*

[220-302](#) *A+ OS TECHNOLOGY (2003 Objectives)*

[220-301](#) *A+ CORE HARDWARE (2003 Objectives)*

[220-304](#) *A+ Core OS Technologies Exam - Arabic or Greek only*

[BR0-003](#) *CompTIA A+ Bridge (2009 Edition) Exam*

[JK0-601](#) *CompTIA E2C A+ Essentials (2007 Edition) Exam*

[220-611](#) *CompTIA A+ Essentials Exam - Arabic only*

JK0-602 *CompTIA A+ 220-602 (2007 Edition) Certification Exam, IT Technician Designation*

JK0-701 *CompTIA E2C A+ Essentials (2009 Edition) Exam*

220-612 *CompTIA A+ 220-602(IT Technician)Exam - Arabic only*

Other CompTIA Exams

<u>JK0-011</u>	<u>CT0-101</u>	<u>JK0-701</u>	<u>PK1-003</u>	<u>220-602</u>	<u>n10-003</u>	<u>sk0-002</u>	<u>JK0-602</u>
<u>220-611</u>	<u>JK0-013</u>	<u>JK0-015</u>	<u>HT0-201</u>	<u>JK0-604</u>	<u>N10-103</u>	<u>FC0-U11</u>	<u>JK0-012</u>
<u>JK0-601</u>	<u>220-601</u>	<u>SY0-201</u>	<u>RF0-001</u>				