

Verified Answers Researched by Industry Experts and almost 100% correct

920-112 exam questions updated on regular basis

Same type as the certification exams, 920-112 exam preparation is in multiple-choice questions (MCQs).

Tested by multiple times before publishing

Try free 920-112 exam demo before you decide to buy it in Test-Inside.com.

Note: This pdf demo do not include the question's picture.

Exam : Nortel 920-112

Title : NNCSS Media Processing Server(MPS)500-Technical Support

1. Other than the Vshell, where else can the first character timer be set for a single line?

- A. tms.cfg
- B. wm.cfg
- C. MPSConfigurator
- D. PeriProducer application

Answer: D

2. Which service would you use to stop and start the Startup and Recovery Process (SRP)?

- A. Nortel Networks Startup Service
- B. Nortel Networks License Service
- C. Nortel Networks Shutdown Service
- D. Nortel Networks Remote Shell (RSH) Service

Answer: A

3. Which software packages are part of a typical software installation on the Media Processing Server (MPS) 500?

(Choose three.)

- A. PERIrd
- B. PERIplic
- C. PERIweb
- D. PERIpstu

Answer: ABD

4. A technician needs to allow phone lines 1-24 to communicate to Host 1, and phone lines 25-48 to communicate to Host 2. Which command set will allow the technician to enable this configuration?

- A. h1 p 1-24 host 1 and h1 p 25-48 host 2
- B. h1 p 1-24 host 1 and h2 p 25-48 host 2
- C. h1 p 1-24 session 1 and h1 p 25-48 session 2
- D. h1 p 1-24 session 1 and h2 p 25-48 session 2

Answer: D

5. When a Media Processing System (MPS) 500 system is started, which file would you use to activate a multimedia file for recording?

- A. vmm-cmr.cfg
- B. vmm-mmf.cfg
- C. vmm-rec.cfg
- D. vmm-smp.cfg

Answer: B

6. A technician sees the following output on an Application Processor monitor. VMM: Initiating deactivation of MMF [NUMDEMO] VMM: Successfully deactivated [NUMDEMO] Which command did the technician enter to show this

output?

- A. vmm deactivate numdemo
- B. vmm mmfrecord numdemo
- C. vmm mmfunload numdemo
- D. vmm mmfdeactive numdemo

Answer: C

7. A technician enters the Media Processing Server (MPS) 500 Chassis ID switch by reading into the tms.cfg file. Which statement in this file is used?

- A. BIND
- B. RSET
- C. LOAD
- D. CHASSIS

Answer: A

8. A technician receives a replacement TMS assembly from the parts depot. The technician makes all the necessary connections to the Application Processor, but the TMS assembly will NOT boot. What action will boot the Media Processing Server (MPS) 500?

- A. Edit the bootptab file with the new IP address of the TMS assembly.
- B. Edit the hosts file with the new Ethernet address of the TMS assembly.
- C. Edit the ethers file with the new Ethernet address of the TMS assembly.
- D. Edit the bootptab file with the new Ethernet address of the TMS assembly.

Answer: D

9. A 24-port Media Processing Server (MPS) 500 is being upgraded to a 48-port system. Which three configuration files will be changed? (Choose three.)

- A. tms.cfg
- B. plservc
- C. ccm.cfg
- D. vpshosts

Answer: ABC

10. A Media Processing Server (MPS) 500 Administrator wants access to the Nortel Networks online product documentation. Which package must be installed?

- A. PERIntp package
- B. PERIdoc package
- C. PERImps package
- D. PERImpsdoc package

Answer: B

11. What is the default target directory for software installations on the Media Processing Server (MPS) 500?

- A. Nortel
- B. ProgramsNortel
- C. Program FilesNortel
- D. Program FilesNortelPeriProducts

Answer: C

12. Which path and file must contain entries for all of the Network interfaces on the MPS 500?

- A. hosts
- B. etchosts
- C. WinntSystem32hosts.cfg
- D. WinntSystem32drivershosts

Answer: D

13. A technician is configuring a Media Processing Server (MPS) 500 and wants to allow an application to be notified if the host does NOT respond after 30 seconds. Which configuration will enable this requirement?

- A. h1 p 1-24 er 30
- B. h1 p 1-24 ertimer 30
- C. h1 p 1-24 ertimeout 30
- D. h1 p 1-24 ermaxtime 30

Answer: A

14. Once the XVISION software is installed on an Application Processor, what element requires configuration to work with the Media Processing Server (MPS) 500 software?

- A. Vision Services
- B. XVISION Server
- C. XVISION Profiles
- D. Vision Communications

Answer: D

15. A technician configures the tms.cfg file for two spans on a Media Processing Server (MPS) 500 system. Which configuration file needs to be modified to associate the Call Control Manager (CCM) with 48 phone lines?

- A. vos.cfg
- B. ase.cfg
- C. gen.cfg
- D. tms.cfg

Answer: A

[More 920-112 Information](#)

Related 920-112 Exams

[922-109](#) *Communications Server 1000 RIs.6.0 BARS/NARS*

[922-101](#) *Communication Server 1000 Linux Platform Architecture*

[922-111](#) *Communication Server 1000 to RIs.6.0 Upgrades for Technicia*

[922-081](#) *CallPilot RIs.5.0 Networking*

[920-457](#) *CallPilot RIs.4.0 Unified Messaging Exam*

[922-104](#) *Communication Server 1000 RIs.6.0 Upgrades for Engineers*

[922-071](#) *BCM50 RIs.3.0 & BCM200/400 RIs.4.0 Config & Maintenance*

[920-110](#) *NCCSS SL-100 Maintenance Certification Exam*

[922-098](#) *Communication Server 1000 RIs.5.0 Troubleshooting*

[920-805](#) *Nortel Data Networking Technology*

[920-806](#) *Nortel Advanced Data Networking Technology*

[920-220](#) *Nortel Converged Campus ERS Solution*

[920-502](#) *nncss-optera metro 3000*

[920-569](#) *nncds-optera metro solutions*

[920-246](#) *Nortel WLAN 2300 RIs.5.0 Implementation & Management*

[920-520](#) *Nortel Agile Communication Environment (ACE) RIs. 1.x Design & Engineering*

[922-099](#) *Communication Server 1000 RIs.5.0 Linux Platform Base & App*

[922-094](#) *Communication Server 1000 RIs.5.0 Dialing Plan Design & IP*

[920-197](#) *BCM50 RIs.2.0 & BCM200/400 RIs.4.0 Config & Maintenance*

[920-199](#) *BCM50 RIs. 2.0 & BCM200/400 RIs. 4.0 ICM*

Other Nortel Exams

<u>922-093</u>	<u>920-132</u>	<u>922-110</u>	<u>920-181</u>	<u>922-031</u>	<u>920-331</u>	<u>922-020</u>	<u>920-226</u>
<u>920-115</u>	<u>920-453</u>	<u>920-361</u>	<u>920-250</u>	<u>920-231</u>	<u>920-470</u>	<u>920-177</u>	<u>920-180</u>
<u>920-436</u>	<u>920-328</u>	<u>920-442</u>	<u>920-139</u>				